



## Space Shuttle SR&QA Assessment

Presenter **M. D. Erminger**

Date **August 29, 2000** Page **1**

# STS-106

# Flight Readiness Review



## Space Shuttle SR&QA Assessment

Presenter **M. D. Erminger**

Date **August 29, 2000** Page **2**

# Approach and General Description

**SR&QA held reviews in preparation for the STS-106 Flight Readiness Review on 14 August and 24 August 2000 and is ready to proceed toward launch countdown.**

## FRR Briefing Overview

- **Significant assessments - *discuss***
- **Special topics**
  - **NASA Safety Reporting System (NSRS) - *discuss***
  - **Hazard Analysis - *discuss***
  - **Failure Modes and Effects Analysis/Critical Items List (FMEA/CIL) - *discuss***
- Significant Open work - *none*
- CoFR Exceptions - *none*
- Open Action Items - *none*



## Space Shuttle SR&QA Assessment

Presenter **M. D. Erminger**

Date **August 29, 2000** Page **3**

# **Significant Assessments**

## Orbiter

- **Ku-Band Radiating Inside the EVA Box During STS-101**
  - No ISS Hardware concern for STS-106
  - Ku-Band radiated RF power level in RF protect box does not pose a risk to EVA crewmembers or EMU
    - Power density from Ku-Band 15 GHz radiation is 30 mW/cm<sup>2</sup>
    - Ku-Band can not radiate for more than 0.03 minutes in RF protect box, more than a factor of ten below crew safety limits
  - The Instrumentation & Communications officer will manage the Ku-Band system by using stored program commands to preclude RF radiation while pointing into the RF protect box



## Space Shuttle SR&QA Assessment

Presenter **M. D. Erminger**

Date **August 29, 2000** Page **4**

# **Significant Assessments**

### Orbiter (continued)

- **RCC Panel #7 Found Damaged Post STS-101**
  - Implemented corrective actions for gap filler installation prior to STS-106
    - Added position markings to aid in position verification
    - Certified technicians reinstalled and tested the RCC panels and replacement gap fillers
  - Tested and inspected surrounding structural hardware and is acceptable for flight
- **Anti-Flood Valve Contamination Found Post STS-101**
  - No risk of particle ignition impact from SSME operation
  - Any remaining contamination is too small to restrict flow through the flow control valves
  - No evidence of contamination on STS-106



## Space Shuttle SR&QA Assessment

Presenter **M. D. Erminger**

Date **August 29, 2000** Page **5**

# **Significant Assessments**

## **EVA**

- **Oil Contamination of the EMU Oxygen Systems**
  - Cleaned all STS-106 Secondary Oxygen Pack (SOP) regulators prior to flight
  - Primary Life Support System (PLSS) testing demonstrates that ignition is highly improbable
  - Controls are in place to preclude future occurrences
  - SR&QA will issue a Safe ALERT when root cause is identified

## **ET**

- **Weld Bead Dressing**
  - Sanding/shaving weld bead penetrant indications could result in unacceptable weld strength
  - Discovered during NASA Engineering Quality Audit (NEQA)
  - STS-106 welds meet initial weld properties with shaved beads
  - Test and analysis demonstrate positive margins of safety for all welds



## Space Shuttle SR&QA Assessment

Presenter **M. D. Erminger**

Date **August 29, 2000** Page **6**

# **Significant Assessments**

## **SRB**

### **• CDF Initiator Electrical Bond Check Not Performed**

- Initiators installed on STS-106 forward BSM and Nose Cap thrusters
- Worst case failure effect is criticality 1, premature operation leading to loss of crew/vehicle
- Rationale for Flight
  - To date 768 aft BSM CDF initiator installations have been checked and none have failed the electrical bonding requirement
    - Using statistical analysis, probability of achieving an electrical bond is 0.9991
  - The design and installation processing of the forward CDF initiators are the same as the aft BSM initiators
  - CDF initiator mating surfaces are metal to metal contact
  - Testing confirmed insensitivity to electrostatic discharge



## Space Shuttle SR&QA Assessment

Presenter **M. D. Erminger**

Date **August 29, 2000** Page **7**

# **Significant Assessments**

## **SRB (continued)**

- **Forward Skirt Range Safety System Transition Assembly Weld Anomaly**
  - Suspect welds are not full penetration welds
  - Criticality 1 – Loss of thermal protection resulting in debris generation and possible hot gas path to RSS cables
  - Welds are in a low stress area
  - Re-verified flight environment loads
  - Proofload tested assemblies from the same buy to worst case conditions

## **SSME**

- **Engine 0523 Mishap**
  - Premature cutoff during a test at SSC was due to a violation of the High Pressure Fuel Turbine discharge temperature LCC
  - Failure analysis identified cause of shutdown to be “LOX Tape”
    - Used to cover open orifices during processing



## Space Shuttle SR&QA Assessment

Presenter **M. D. Erminger**

Date **August 29, 2000** Page **8**

# **Significant Assessments**

## **SSME (continued)**

- **Engine 0523 Mishap (continued)**
  - Criticality 1 Failure Mode
    - Failure of HPFT/AT turbine blade airfoils could result in rotor imbalance and pump failure resulting in uncontained engine damage and loss of vehicle
  - To re-verify barrier removal, all joints where contamination barriers were used for STS-106 were identified and inspected
  - One joint, O2, LPOTP discharge duct to LPOTP, could not be inspected
  - Rationale for not opening joint O2 was approved by the SSP
    - No joint lapping during processing
    - Temporary closures used and vertical orientation makes FOD introduction difficult
    - Temporary closure prevents bolt installation
    - Joint easily inspected and verified during assembly
    - Joint passed bubble leak check and encapsulation test

***ADDITIONAL ASSESSED ITEMS ARE IN THE BACKUP CHARTS***





**Space Shuttle SR&QA Assessment**

Presenter **M. D. Erminger**

Date **August 29, 2000** Page **9**

**NSRS Summary**

**There are no NASA Safety Reporting System reports open that are applicable to STS-106.**



**Space Shuttle SR&QA Assessment**

Presenter **M. D. Erminger**

Date **August 29, 2000** Page **10**

## **Hazard Analysis Summary**

**There are no new Accepted Risk hazards identified for STS-106.**



## Space Shuttle SR&QA Assessment

Presenter **M. D. Erminger**

Date **August 29, 2000** Page **11**

# **FMEA/CIL Summary**

## **Orbiter**

### **Five failure modes associated with the landing gear circuit**

- A one flight waiver to CIL submittal requirements has been approved by the PRCB to allow time to document new CIL failure modes
  - Two existing connector failure modes undocumented for MEDS configuration
    - Nose Landing Gear extension pyro assist circuit
      - Connector plug inadvertent demate, Criticality 1/1
    - Main Landing Gear down command circuit
      - Connector plug pin-to-pin short, Criticality 1/1
  - Risk assessment
    - Reliable connector design with robust test and inspection
    - Visual inspection of STS-106 confirmed connector mate and locking bayonets visible for the NLG extension pyro circuit
    - Exposure is less than one minute for the MLG pin-to-pin short and requires worst case flight profile



## Space Shuttle SR&QA Assessment

Presenter

**M. D. Erminger**

Date

**August 29, 2000**

Page 12

# **FMEA/CIL Summary**

## Orbiter

### **Five failure modes associated with the landing gear circuit (continued)**

- Three new failure modes associated with the MLG down control circuit
  - One new relay short to structure failure mode for the MLG down control circuit
    - Latching relay prematurely closes deploying MLG as soon as “arm” command is set, Criticality 1/1
  - Two new diode failure modes, end to end short and short to structure for the MLG down control circuit
    - Blocking diode failures combine to disable the MLG extend valve (loss of hydraulic deploy), Criticality 1R3
- Risk assessment
  - Reliable connector and diode design with robust test and inspection
  - No flight failure history



**Space Shuttle SR&QA Assessment**

Presenter **M. D. Erminger**

Date **August 29, 2000** Page **13**

## **STS-106 Readiness Statement**

**With the satisfactory completion of identified open work, Safety, Reliability, and Quality Assurance has no constraints to STS-106. SR&QA has no issues that constrain any of the mission success criteria.**

**/s/ J. H. Casper**  
**SR&QA Director, JSC**

**/s/ Shannon Bartell**  
**Director, KSC Safety, Health  
and Independent Assessment**

**/s/ A. H. Goodson**  
**S&MA Director, MSFC**

**/s/ B. Higgins**  
**Chief, Shuttle S&MA, KSC**

**/s/ M. D. Erminger**  
**SS SR&QA Manager**

**/s/ H. Davis**  
**HEDS IA Director**



**Space Shuttle SR&QA Assessment**

Presenter

**M. D. Erminger**

Date

**August 29, 2000**

Page **B-1**

**STS-106**

**Flight Readiness Review**

**Backup Package**



## Space Shuttle SR&QA Assessment

Presenter **M. D. Erminger**

Date **August 29, 2000** Page **B-2**

# **Additional Assessments**

## Orbiter/GFE

- First flight of Advanced Master Events Controller (AMEC)
- STS-101 Left Orbital Maneuvering System (OMS) Bi-propellant Valve Anomaly
- STS-101 Meds Multifunction Display Unit (MDU) Crt 1 And 2 Innocuous Events
- STS-101 Speedbrake Channel 3 Pressure Hesitation During FCS Checkout
- RMS MPM Stow Problem
- OV-102 Main Landing Gear (MLG) Bungee Rivet Failure
- OV-105 LP04 Oxidizer Tee Assembly Pinhole Leak
- Landing Gear Inadvertent Demate/hydraulics System 2 Nose Landing Gear Deploy
- OV-105 ODS Petal #2 Alignment Anomaly
- Improper Rigging Of Skygenie During Post Landing Egress Training
- OV-104 Left Orbital Maneuvering Engine (OME) Gimbal Actuator Noise
- Quality Control Cleaning Corporation Issue
- Night Crosswind Limit Expansion For Transatlantic Abort Landing (TAL) Sites
- Collins Tactical Air Navigation (TACAN) Concern
- OV-104 Liquid Hydrogen (LH2) Manifold Convolute Pinhole



## Space Shuttle SR&QA Assessment

Presenter **M. D. Erminger**

Date **August 29, 2000** Page **B-3**

# **Additional Assessments**

### **Orbiter/GFE (continued)**

- Main Hydraulic Pump Depressurization Piston Cap Bolt Configuration
- Launch Window Management
- NSTS 8080-1 Waiver, Standard 134, Electrical Power Distribution Circuits – Overload Protection For The Orbiter Space Vision Unit (OSVU)
- MPS Fill And Drain Valve Loose Shim
- CRES/IRED Acceptance Rationale

### **ET**

- Aft Fairing Closeout
- Thrust panel penetrant inspection

### **SSME**

- HPOTP/AT Joint G3 Blistered Seal
- QCCC Cleaning Issues
- Anti-Flood Valve Contamination





## Space Shuttle SR&QA Assessment

Presenter **M. D. Erminger**

Date **August 29, 2000** Page **B-4**

# **Additional Assessments**

### **RSRM**

- First Flight / Critical Process Change
  - Case Buckling Certification
  - Elimination of Requirement to Weekly Verify Sodium Tripolyphosphate Concentration (STTP)
- Corrective Actions for Nozzle Pocketing Erosion
- STS-101 Ignition S&A Device Damaged A-M Motor Armature
- Suspect Paraffin and Silicone Contamination of Flight Hardware
- S&A Barrier Booster Basket Pellet Contamination

### **SRB**

- Drogue Parachute Reefing Line Cutter Shelf Life Expiration
- SWAR Batteries Shelf Life
- STS-101 APU Gear Box Lube Oil Contamination
- Rate gyro assembly (RGA) maintenance requirements not performed
- CDF initiator bond check not performed

### **Launch & Landing**

- Wire Crimping Issue